

a.



b.



c.



d.



e.



f.



Plate 6. Erosion issues, Caboolture River: a & b) bare river banks with erosion evident in intertidal zone; c) mature mangroves overhanging river; d) pneumatophores (peg roots) of mangroves stabilising the shoreline; e) onsite erosion from unauthorised vehicles; f) car dumped in the Caboolture River on project site upstream of entrance to proposed marina basin.